

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

IC1164  
West  
> 1  
1.538 mi.  
8122 ft.

**SPILL NUMBER 0010061**  
**HIGHLAND AV & LINE AV**  
**BROOKLYN, NY**

**NY Spills S104879688**  
**N/A**

**Site 2 of 2 in cluster IC**

**Relative:**  
**Higher**

**Actual:**  
**0 ft.**

**SPILLS:**

Name: SPILL NUMBER 0010061  
Address: HIGHLAND AV & LINE AV  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0010061 / 2009-08-18  
Facility ID: 0010061  
Facility Type: ER  
DER Facility ID: 232766  
Site ID: 287342  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2000-12-06  
Investigator: JMKRIMGO  
Referred To: Not reported  
Reported to Dept: 2000-12-06  
CID: 365  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2000-12-06  
Spill Record Last Update: 2009-08-18  
Spiller Name: Not reported  
Spiller Company: CON EDISON  
Spiller Address: 4 IRVING PLACE  
Spiller Company: 001  
Contact Name: Not reported  
DEC Memo: "08/18/09 - See eDocs for Con Ed report detailing cleanup and closure. Prior to Sept, 2004 data translation this spill Lead\_DEC Field was O'CONNELL e2mis notes: 12/6/2000 16:15, 1 drop of dielectric fluid dripping every 5 minutes. Absorbed into the dirt of the floor. Transformer pressure tested and failed. Transformer not below minimum level. Sample taken from transformer. Historical records 10 ppm. Tanker to be dispatched to drain the transformer. Transformer to be replaced in am. 12/6/2000 21:45 hrs. All liquid have been drained from transformer ( 200 gallons). All liquid was removed from the structure. Transformer to be removed in morning. Cleanup will be completed when transformer is removed and results come back. 12/7/2000 2100 hrs, Reports transformer removed by Equip. Gp. Solid waste replaced into three barrels that were picked up by Astoria Transportation for disposal. Sump found cemented. Structure double washed with Bio-Gen 760. No leaking company equipment."

**Remarks:**

"TRANSFORMER FAILED THE PRESSURE TEST - 1 DROP EVERY 5 MINUTES CLEAN UP WILL BE HANDLED AT 50-499 PPM PCB'S - CLEAN UP WILL START AS SOON AS TRANSFORMER IS DRAINED DOWN - REF#134644 LAB RESULTS THE UPDATE WAS DONE 12/07/2000 01:27AM 52 PPM PCB "

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

All Materials:

Site ID:	287342
Operable Unit ID:	831037
Operable Unit:	01
Material ID:	543984
Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported